




Pressure and vacuum gauges


Pressure gauges

## Pressure gauge DN 63 vertical connection with glycerin (1/4" BSP)

Page: 1/2







Accuracy: 1,6%

**Dimensions:** A=68 B=29,8 D=54,5

B=29,8 D=54,5 F=HEX 14 G=9,5

Temperature: from -20 up to +60

Part nº	R1	Scale (bar)
MFI6304001V	1/4" BSP	0-1
MFI63042.5V	1/4" BSP	0-2.5
MFI6304004V	1/4" BSP	0-4
MFI6304006V	1/4" BSP	0-6
MFI6304010V	1/4" BSP	0-10
MFI6304012V	1/4" BSP	0-12
MFI6304016V	1/4" BSP	0-16
MFI6304020V	1/4" BSP	0-20
MFI6304025V	1/4" BSP	0-25
MFI6304040V	1/4" BSP	0-40
MFI6304060V	1/4" BSP	0-60
MFI6304100V	1/4" BSP	0-100
MFI6304160V	1/4" BSP	0-160
MFI6304250V	1/4" BSP	0-250
MFI6304315V	1/4" BSP	0-315
MFI6304400V	1/4" BSP	0-400

Printed on: 12/05/2018 at 06:33





Pressure and vacuum gauges
Pressure gauges

## Pressure gauge DN 63 vertical connection with glycerin (1/4" BSP)

Page: 2/2

Part nº	R1	Scale (bar)
MFI6304600V	1/4" BSP	0-600
MFI63041000V	1/4" BSP	0-1000

\*\*\* Review attached PDF\*\*\*

With dual bar/psi scale

Printed on: 12/05/2018 at 06:33